

Inspection Report

Report Number: 586719

Report Generated For Customer: Rosa Subirat

Date of Inspection: 7/20/2023

Location of Inspection: Las Vegas, NV, 89138

For Questions, call us at (866) 935-2057 or email us at services@lemonsquad.com

Important Disclosures:

This Inspection Report is governed by the terms and conditions of the order which are available at <https://lemonsquad.com/terms> and which contain important information, disclosures, and disclaimers.

This Inspection Report is for the sole and exclusive use of the Customer named above and may not be used or relied upon by any third party including, without limitation, any purchaser of a vehicle from Customer.

Without limiting the Limited Warranty, Disclaimers, Limitations on Liability and Dispute Resolution provisions of the terms and conditions (available at <https://lemonsquad.com/terms>), there are no implied or express warranties or guarantees of any kind in connection with any vehicle inspection. The vehicle inspection is intended solely as an "evaluation" of a given vehicle's condition at the time, date and place of examination. Wrench Inc., and its affiliates including LemonSquad, specifically disclaims any liability for any loss or damage arising in connection with ownership or operation of said vehicle and further disclaims any liability of any hidden wreck, flood damage or tampered components not readily apparent upon visual inspection. The items visually inspected were in the reported condition listed in the report at the time of the inspection only. A visual inspection will not identify the working condition of each and every vehicle part or component, nor will a visual inspection identify any or all missing, tampered or altered components. Intermittent component or systems issues or failures may not present themselves at the precise time of inspection and/or a vehicle may be tuned in a manner to mask or minimize any such issues; in either case, such intermittent issues may not be discoverable during inspection. Further disclaimed is any liability for any damage or defects not found during inspection. Other conditions may exist which did not occur or appear during inspection. It is the customer's responsibility to ensure the vehicle to be inspected is in a state in which the vehicle is legal to drive on public roads, safe and functioning well enough to start and drive, and located in a space that is accessible and allows the inspector full access to vehicle components. Vehicles that are not safe, legal, or in a running condition will not have a test drive performed. Inspection reports are for information only and are not to be considered a recommendation for or against the purchase of the inspected vehicle.

Report #586719

1982 Toyota Fj43



Summary

1982 Toyota Land Cruiser

The vehicle started easily. No knocking or ticking could be heard coming from the motor. There are no exhaust leaks. No smoke was seen. Belts and hoses are in good condition. All the fluids are full. The oil is clean, and no oil sludge was found. The wiring is good including the clips and connectors. No fluid leaks were found. It holds a rev well.

It ran well while I test drove it. It has plenty of power. The manual transmission went into each gear easily. The clutch is firm. The 4-wheel Lo and Hi engages as it should. There are no unusual squeaks or vibrations heard. The steering is good and tight. The brakes stop firmly when needed. This is a non-smokers vehicle.

The paint shines nicely. The body lines and gaps look good. Doors open and close just fine - so does the sliding glass side windows. The glass is good all around. All lights work including the turn signals. No rust was found. Floorboards are solid front to back. The backdoor key does not unlock.

The headliner, sun-visors and dash are in good condition. The AC blows cold, and the heat works too. All buttons and switches work as well. Windows manually roll up and down smoothly. The wipers work.

The suspension performed well as expected on the test drive. The tie rods and bushings looked good. The shocks and springs are in good condition. The ball joints are good too. No frame damage was found.


The wheels are in good condition. No curb rash was found.

This vehicle shows pride of ownership.

Vehicle Information

| | |
|---------------------|------------------|
| Year | 1982 |
| Make | Toyota |
| Model | Fj43 |
| VIN | FJ43108232 |
| Stock No. | N/A |
| Mileage | 3490 |
| Fuel Type | Gas |
| Engine Cylinders | 6 Cylinder |
| Interior Color | Tan |
| Exterior Color | Blue |
| Interior Material | Leather |
| Transmission | Manual |
| Drive Type | Four Wheel Drive |
| Engine Number | N/A |
| Transmission Number | N/A |










Road Test

| | |
|------------------------------------|--|
| Road Test | Yes |
| Engine Starting Easily |  Good |
| Engine running well after Started |  Good |
| Transmission performance |  Good |
| Clutch Performance |  Good |
| Differential Performance |  Good |
| Transfer Case Performance |  Good |
| Wheel Bearing Performance |  Good |
| Braking Performance |  Good |
| Suspension Performance |  Good |
| Steering Performance and Alignment |  Good |


























Exterior

| | |
|---------------------------|--|
| Wiper Blades |  Good |
| Back-Up Camera |  Good |
| Windshield Washer |  Good |
| Body Panel Alignment |  Good |
| Scratches |  Good |
| Paint Condition |  Good |
| Seals |  Good |
| Rust |  Good |
| Exterior Lights |  Good |
| Power Door Mirrors |  Good |
| Bumpers |  Good |
| Side Moldings |  Good |
| Underbody/Frame Condition |  Good |
| Glass |  Good |
| Floors |  Good |
| Rockers |  Good |
| Quarter Panels |  Good |
| Hood |  Good |
| Doors |  Good |
| Dings |  Good |
| Dents |  Good |

Interior

| | |
|---------------------------|--|
| Steering Wheel |  Good |
| Horn |  Good |
| Cruise Control |  Good |
| Seat Condition |  Good |
| Seat Belts |  Good |
| Clock |  Good |
| Inner Door Panels |  Good |
| Center Console |  Good |
| Dash |  Good |
| Dash Lights Working |  Good |
| Air Conditioning |  Good |
| Heater |  Good |
| Floor Mats |  Good |
| Signs of Smoking? |  Good |
| Cup Holders |  Good |
| Headliner |  Good |
| Blower Motor |  Good |
| Instrument Cluster/Gauges |  Good |
| Unusual Odors |  Good |
| Window Function |  Good |
| Interior Trim |  Good |
| Inner Trunk Condition |  Good |
| Sun Visors |  Good |

Mechanical

| | |
|---|--|
| Radiator Cap Sealing Properly |  Good |
| Air Filter |  Good |
| Battery Condition |  Good |
| Coolant Leaks |  Good |
| Charging System |  Good |
| Cooling Fan Condition Mechanical/Electronic |  Good |
| Hoses and Clamps Age/Cracking |  Good |
| Radiator Condition |  Good |
| Engine Coolant Condition |  Good |
| Belts |  Good |
| Power Steering System |  Good |
| Power Steering Fluid Condition |  Good |
| Engine Oil Condition |  Good |
| Engine Oil Leaks |  Good |
| Transmission Fluid Condition |  Good |
| Transmission Fluid Leaks |  Good |
| Brake System Condition |  Good |
| Brake Fluid Leaks |  Good |
| Transfer Case Leaks |  Good |
| Differential leaks |  Good |
| Muffler System |  Good |
| CV Boots and Joints |  Good |
| Shocks and bushings Condition. Leaking? |  Good |
| Ball Joints and Tie Rods |  Good |
| Modifications |  Good |

Tire / Wheels

| Manufacturer | |
|---------------------------------|-------------|
| Driver's Front Tire | BF Goodrich |
| Passenger's Front Tire | BF Goodrich |
| Driver's 1st Axle Outer Tire | BF Goodrich |
| Passenger's 1st Axle Outer Tire | BF Goodrich |
| Size | |
| Driver's Front Tire | LT265/75R16 |
| Passenger's Front Tire | LT265/75R16 |
| Driver's 1st Axle Outer Tire | LT265/75R16 |
| Passenger's 1st Axle Outer Tire | LT265/75R16 |
| Axle Count | |
| Tire Condition | |
| Driver's Front Tire | No Issues |
| Passenger's Front Tire | No Issues |
| Driver's 1st Axle Outer Tire | No Issues |
| Passenger's 1st Axle Outer Tire | No Issues |
| Wheel Condition | |
| Driver's Front Tire | No Issues |
| Driver's 1st Axle Outer Tire | No Issues |
| Passenger's Front Tire | No Issues |
| Passenger's 1st Axle Outer Tire | No Issues |
| Tire Tread | |
| Driver's Front Tire | 14/32 |
| Passenger's Front Tire | 14/32 |
| Driver's 1st Axle Outer Tire | 14/32 |
| Passenger's 1st Axle Outer Tire | 14/32 |
| Spare Tire | |
| | Yes |

Vehicle Images







5612 before test drive





Engages




















5616 after test drive



























G43


Heritage



#1116

FJCO ID: 82CB43-1116
FRAME NUMBER: FJ43-108232
MECH ID: JTFU-73J7J7069816

























G43


Heritage




#1116

FJCO ID: 82CB43-1116
FRAME NUMBER: FJ43-108232
MECH ID: JTFU-73J7J7069816































































































































TPGS 77 111 000
TS ASAH
A82 DOT-20 M224
R6520 J T
VW 0500




































































Explore maintenance, repair and inspection services here.

Lemon Squad[™]
BY  **WRENCH**

 **WRENCH**