

Inspection Report

Report Number: 571971

Report Generated For Customer: Rosa Subirat

Date of Inspection: 5/30/2023

Location of Inspection: Fayetteville, NC, 28303

For Questions, call us at (866) 935-2057 or email us at services@lemonsquad.com

Important Disclosures:

This Inspection Report is governed by the terms and conditions of the order which are available at <https://lemonsquad.com/terms> and which contain important information, disclosures, and disclaimers.


This Inspection Report is for the sole and exclusive use of the Customer named above and may not be used or relied upon by any third party including, without limitation, any purchaser of a vehicle from Customer.

Without limiting the Limited Warranty, Disclaimers, Limitations on Liability and Dispute Resolution provisions of the terms and conditions (available at <https://lemonsquad.com/terms>), there are no implied or express warranties or guarantees of any kind in connection with any vehicle inspection. The vehicle inspection is intended solely as an "evaluation" of a given vehicle's condition at the time, date and place of examination. Wrench Inc., and its affiliates including LemonSquad, specifically disclaims any liability for any loss or damage arising in connection with ownership or operation of said vehicle and further disclaims any liability of any hidden wreck, flood damage or tampered components not readily apparent upon visual inspection. The items visually inspected were in the reported condition listed in the report at the time of the inspection only. A visual inspection will not identify the working condition of each and every vehicle part or component, nor will a visual inspection identify any or all missing, tampered or altered components. Intermittent component or systems issues or failures may not present themselves at the precise time of inspection and/or a vehicle may be tuned in a manner to mask or minimize any such issues; in either case, such intermittent issues may not be discoverable during inspection. Further disclaimed is any liability for any damage or defects not found during inspection. Other conditions may exist which did not occur or appear during inspection. It is the customer's responsibility to ensure the vehicle to be inspected is in a state in which the vehicle is legal to drive on public roads, safe and functioning well enough to start and drive, and located in a space that is accessible and allows the inspector full access to vehicle components. Vehicles that are not safe, legal, or in a running condition will not have a test drive performed. Inspection reports are for information only and are not to be considered a recommendation for or against the purchase of the inspected vehicle.

Report #571971



2007 Ford SHELBY MUSTANG GT500



Summary

Exterior

There were no dents and the paint looked good overall for the age and mileage of the vehicle. The wipers and exterior lights worked.

Interior

The seats were clean and I noted tears or rips.

The door panels and interior trim showed the age and mileage of the vehicle.

I noted no no smoke or odd odors. The interior electronics and climate controls worked.

The windows, locks, and mirrors all functioned. The gauges worked.

Mechanical

I noted full accessible fluids. I noted no visual leaks.

Test Drive

I noted good acceleration. The transmission worked as designed.












The vehicle handled and braked well. I noted no odd noises or vibrations.

No DTC faulty codes found during inspection.














Vehicle Information

Year	2007
Make	Ford
Model	Shelby mustang gt500
VIN	1ZVHT89S375208770
Stock No.	208770
Mileage	6977
Fuel Type	Gas
Engine Cylinders	8 Cylinder
Interior Color	Black
Exterior Color	Red
Interior Material	Leather
Transmission	Manual
Drive Type	Rear Wheel Drive



























Road Test

Road Test	Yes
Engine Starting Easily	 Good
Engine running well after Started	 Good
Transmission performance	 Good
Clutch Performance	 Good
Differential Performance	 Good
Wheel Bearing Performance	 Good
Braking Performance	 Good
Suspension Performance	 Good
Steering Performance and Alignment	 Good
Tire Pressure System (TPMS)	 Good
Computer Diagnosis/OBD2	 Good























Exterior

Back-Up Camera	 Good
Wiper Blades	 Good
Windshield Washer	 Good
Body Panel Alignment	 Good
Scratches	 Good
Paint Condition	 Good
Seals	 Good
Rust	 Good
Exterior Lights	 Good
Power Door Mirrors	 Good
Bumpers	 Good
Side Moldings	 Good
Convertible Top	 Good
Underbody/Frame Condition	 Good
Glass	 Good
Dings	 Good
Dents	 Good

Interior

Steering Wheel	 Good
Horn	 Good
Cruise Control	 Good
Seat Condition	 Good
Heated Seats	 Good
Seat Belts	 Good
Clock	 Good
Radio/Navigation/DVD	 Good
Inner Door Panels	 Good
Power Locks	 Good
Power Window Switches	 Good
Center Console	 Good
Dash	 Good
Dash Lights Working	 Good
Air Conditioning	 Good
Heater	 Good
Rear Defroster	 Good
Carpet	 Good
Floor Mats	 Good
Signs of Smoking?	 Good
Cup Holders	 Good
Headliner	 Good
Blower Motor	 Good
Instrument Cluster/Gauges	 Good
Unusual Odors	 Good
Window Function	 Good
Interior Trim	 Good
Sun Visors	 Good

Mechanical

Air Filter	 Good
Battery Condition	 Good
Charging System	 Good
Cooling Fan Condition Mechanical/Electronic	 Good
Radiator Cap Sealing Properly	 Good
Hoses and Clamps Age/Cracking	 Good
Radiator Condition	 Good
Engine Coolant Condition	 Good
Coolant Leaks	 Good
Belts	 Good
Power Steering System	 Good
Engine Oil Condition	 Good
Engine Oil Leaks	 Good
Transmission Fluid Leaks	 Good
Brake System Condition	 Good
Brake Fluid Leaks	 Good
Differential leaks	 Good
Muffler System	 Good
CV Boots and Joints	 Good
Shocks and bushings Condition. Leaking?	 Good
Ball Joints and Tie Rods	 Good
Key Fob	 Good

Tire / Wheels

Manufacturer	
Driver's Front Tire	Nitro
Passenger's Front Tire	Nitro
Driver's 1st Axle Outer Tire	Nitro
Passenger's 1st Axle Outer Tire	Nitro
Size	
Driver's Front Tire	285/40/17
Passenger's Front Tire	285/40/17
Driver's 1st Axle Outer Tire	285/40/17
Passenger's 1st Axle Outer Tire	285/40/17
Axle Count	
Tire Condition	
Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Wheel Condition	
Driver's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's Front Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Tire Tread	
Driver's Front Tire	14/32
Passenger's Front Tire	14/32
Driver's 1st Axle Outer Tire	14/32
Passenger's 1st Axle Outer Tire	14/32
Spare Tire	
No	

Vehicle Images














Car coverp





INNOVA®

5110

I/M MONITOR STATUS



INNOVA.COM

ERASE



LINK



DTC

SET

BACK








Spare air compressor


































Ford Motor Company
VEHICLE EMISSION CONTROL INFORMATION

This vehicle conforms to U.S. EPA regulations applicable to 2007 model year new light-duty vehicles and to California regulations applicable to new LEV II passenger cars. OBD II certified.
TWC/HO2S/EGR/SFI/SC/CAC

Adjustments: Spark Plug Gap: See Spec Book. No other adjustments needed.

CATALYST


7W7E-9C485-
PPP




5.4L-Group: 7FMXV05.4VEK
Evap: 7FMXR0185GAK


VACUUM HOSE ROUTING





















































The Shelby GT500 original equipment tires are optimized for performance in both wet and dry conditions. Ford does not recommend using the original equipment tires when temperatures are below 40°F (5°C) or in snow/ice conditions. Consult the Shelby GT500 owner's supplement guide for recommended tires in these conditions.

Les pneus d'origine des modèles Shelby GT500 sont optimisés pour la conduite sur revêtements humides et secs. Ford déconseille d'utiliser les pneus d'origine par températures inférieures à 5° C (40° F) ou sur routes verglées ou enneigées. Consulter le supplément au Guide du propriétaire Shelby GT500 qui indique les pneus recommandés pour de telles conditions.

7F3JA-1532-AA

MFD. BY FORD MOTOR CO.

DATE: 06/06
 FRONT GAWR: 1134KG/2500LB
 GVWR: 2186KG/4820LB
 REAR GAWR: 1066KG/2350LB

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER, AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VIN: 1ZVHT89S375208770 TYPE: Passenger Car
 MAXIMUM LOAD = OCCUPANTS + LUGGAGE = 301KG/664LB
 OCCUPANTS = 4 TOTAL: 2 FRONT, 2 REAR

TIRE (FR): P255/45R18 RIMS (FR): 18 X 9.5J
 (RR): P285/40R18 (RR): 18 X 9.5J
 PRESSURE (FR): 220 kPa/ 32 PSI COLD (RR): 220 kPa/ 32 PSI COLD

1ZVHT89S375208770

TRAILER TOWING - SEE OWNER GUIDE
 EXT PNT: D3

INT TR	TP/PS	R	AXLE	TR	SPR	RC: 27	DSO:
GR	4	9	CG	E	KKKK	7ZF2S	F0031
					CMC	C05	R0081

1200606218302

5U5A-5420472-AA

TI

SEATING


The combined weight and cargo


TIRE	
FRONT	P
REAR	P
SPARE	

5U5A-1532-AA (TLU)













Manuals
























VEHICLE DESCRIPTION

SHELBY

2007 GT500 CONVERTIBLE
4-PASSENGER SPORTS CAR
5.4L 3C 4V V8 ENGINE
6-SPEED MANUAL TRANSMISSION

VIN 1ZVHT89S375208770
EXTERIOR
TORCH RED CLEARCOAT
INTERIOR
BLACK W/RED ACCENT LEATHER

www.fordvehicles.com

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- 18" X 9" BRIGHT MACHINED ALUM WHEELS
- UNDO SHELBY GT500 BADGING
- BLACK CONVERTIBLE TOP PREMIUM CLOTH
- UNIQUE ALUMINUM HORN WITH AIR EXTRACTORS
- REAR DECKLED SPOILER
- FOG LAMPS
- REAR WINDOW DEFROSTER

INTERIOR

- SPORT BUCKET SEATS WITH EMBOSSED COBRA LOGO
- SHAKER 500 AUDIO SYSTEM AM/FM W/ CDX6 & MP3
- LIGHT-TONED CLUSTER GAUGES
- INCL BOOST GAUGE
- AIR CONDITIONING

FUNCTIONAL

- SVT-TUNED SUSPENSION
- REMPO FRONT BRAKES
- 3.75" VENTED DISC & CALIPER
- 6-SPD TREMEC MANUAL TRANS
- DUAL-TUNED STAINLESS STEEL X-PIPE EXHAUST
- HIGH PERFORMANCE TIRES FRONT P285/35ZR18 REAR P285/40ZR18

SAFETY/SECURITY

- ABS/TRACTION CONTROL
- 2ND GEN DUAL FRONT AIRBAGS
- SIDE-MOUNTED AIRBAGS DRIVER & FRONT PASS SEATS
- ILLUMINATED ENTRY
- REMOTE KEYLESS ENTRY
- LATCH CHILD SAFETY SYSTEM
- 24 HR ROADSIDE ASSISTANCE

WARRANTY

- 3YR/36000 BUMPER TO BUMPER

PRICE INFORMATION

STANDARD VEHICLE PRICE \$45,755.00

Manufacturer's Suggested Retail Price

INCLUDED ON THIS VEHICLE

- ORDER CODE 850A-SHELBY CONV
- DRIVER & PASSENGER AIR BAGS
- ANTI-LOCK BRAKES
- TRACTION CONTROL
- POWER 6-WAY DRIVER'S SEAT
- MANUAL AIR CONDITIONING
- ACTIVE ANTI-THEFT SYSTEM

OPTIONAL EQUIPMENT

- CLOTH BLACK CONVERTIBLE ROOF NO CHARGE
- GAS GUZZLER TAX *** 1,300.00
- FRONT LICENSE PLATE BRACKET NO CHARGE
- SHIP THRU 195.00
- SIRIUS SATELLITE RADIO 595.00
- GT500 PREMIER TRIM PACKAGE
- SHELBY WHITE TAPE STRIPE

TOTAL VEHICLE & OPTIONS 47,845.00
DESTINATION & DELIVERY 745.00

Compare this vehicle to others in the FREE FUEL ECONOMY GUIDE available at the dealer.

CITY MPG

15

Age will vary with options,
ns, driving habits and
m. Results reported to
the majority of vehicles
is will achieve between
n the city
n
the

For more information see
WWW.FUELECONOMY.GOV

2007 MUSTANG SHELBY,
5.4 LITER ENGINE, 4V DOHC V8,
FUEL INJECTION,
CATALYST, 6-SPEED MANUAL
TRANSMISSION

HIGHWAY MPG

21

For Comparison Shopping
all vehicles classified as
SEE NOTE BELOW
have been issued mileage ratings
ranging from to mpg city
and to mpg highway.

Estimated Annual Fuel Cost: \$2002

A RANGE OF FUEL ECONOMY VALUES
FOR OTHER VEHICLES CLASSIFIED
AS SUBCOMPACT IS NOT AVAILABLE
AT THIS TIME.

TOTAL MSRP

\$48,5

1ZVHT89S375208770



Ford Extended Service Plan is the ONLY service contract backed by Ford and honored by over 5,100
Ford and Lincoln Mercury Dealers. Ask your dealer for prices and additional details or see our

SHELBY
AMERICAN, INC.
Vehicle Authenticity Certificate

**This is to certify this Shelby vehicle has been
verified and documented by an official
registrar for Shelby American, Inc.**

**Entry has been verified in the
Official Shelby American Registry**

2007 Shelby GT500
VIN: 1ZVHT898375208770


Patterson
ent


Steven Thornton
Registry Director



AWARD

Explore maintenance, repair and inspection services here.

